

Release note – MultiOne Engineering 3.19

In this release the following items were changed (compared to the previous version):

CHANGES

- Added:
 - Support for new (versions of) LED devices

name	version	12nc
LDP-150W 0.3-1.05A IP67	3.0	929002875180
Xi 1100W 1.6-3.8A 400V GV2	1.0	929002200406
XI075C070V118VSY3M	1.0	929002729913
XI075C105V079VSY3M	1.0	929002729813
Xitanium 20W WH 0.15-0.5A 54V TD S CL	2.0	929002828906
Xitanium 36W WH 0.3-1A 54V TD S CL	2.0	929002829006
Xitanium 50W WH 0.7-1.5A 54V TD S CL	2.0	929002829106
Xitanium 36Wm 0.15-1.05A 48V MC 230V	1.3	929002133006
Xi 45W 0.3-1.2A 48V MC FlexTune 230V	1.3	929002827080
Xitanium 42W-a 0.15-1.05A 42V MC 3CW	1.3	929002847406
Xitanium 42W-a 0.15-1.05A 42V MC 3CB	1.3	929002851206
Xitanium 42W-a 0.15-1.05A 42V MC 3CG	1.3	929002851306
Xi FP 220W 0.2-1.0A SNLDAE 230V C170 sXt	1.0	929002852206
Xi LP 100W 0.3-1.05A S1 I155	3.1	929002878980
Xi LP 150W 0.3-1.05A S1 I175	3.1	929002879080
Xi LP 200W 0.3-1.05A S1 I195	3.1	929002879180
Xi LP 100W 0.5-1.5A S1 I155	3.1	929002879280
Xi LP 150W 0.5-1.5A S1 I175	3.1	929002879380
Xi LP 200W 0.5-1.5A S1 I195	3.1	929002879480
Xi FP 75W 0.2-0.7A SNLDAE 230V C133 sXt	3.0	929002872806
Xi FP 75W 0.3-1.0A SNLDAE 230V C133 sXt	3.0	929002872906
Xi FP 75W 0.5-1.5A SNLDAE 230V C133 sXt	3.0	929002873006
Xi FP 110W 0.2-0.7A SNLDAE 230V C133 sXt	3.0	929002873106
Xi FP 110W 0.3-1.0A SNLDAE 230V C133 sXt	3.0	929002873206
Xitanium 90W 0.25-0.7A 220V TD21 230V	1.1	929001694706
Xitanium 90W 0.25-0.7A 220V TD21 S 230V	1.1	929001694806
Xitanium 90W 0.25-0.7A 300V TD21 S 230V	1.1	929001694906

Improved functionality

- Solved some minor bugs.
- Improved Diagnostics bin range diversity.
- Improved DiiA Part253 Diagnostics & Maintenance, hide non-applicable values.

IMPORTANT NOTICE

Make sure that also the extra conditions are fulfilled:

- User Software Key on line or off line installed (no action needed if PC already has a key)
- Put the *Power mode* of your PC settings in *best performance*.
- The correct Microsoft Windows version,
 - o No Windows XP support
 - o When running the installer on Windows 10, a 'Do not run' button might be shown as the application is not signed. Go to 'more info' to force installation.

The MultiOne software is tested on a wide variety of virus scanners (latest versions), no issues detected.

Document: 30-03-2021
No: RNE7 2021v1
Author: E. Bos