

#	COMPONENT	QTY
1	GLASS	1
2	SCREW	3
3	COVER	1
4	SCREW	1
5	LIGHT SOURCE - HUE CONECT	1
6	HEAT SINK	1
7	SCREW	4
8	CONTROL GEAR - PSU	1
9	SCREW	2
10	BODY	1
11	FLAT CABLE	1
12	LIGHT SOURCE - LED MODULE	1
13	SCREW	3
14	CLOSED END CONNECTOR	2

Warnings

Always make sure the luminaire is detached from the mains socket Always make sure the DC cable is detached from the power supply Staring at the operating light source may cause eye injury

#	Disassemble/dismantle steps	Tools need
а	REMOVE THE GLASS (1)	-
b	REMOVE COVER (3) FROM THE BODY (10) BY UNSCREWING THE SCREWS (2)	CROSS HEA
С	REMOVE THE CLOSED END CONNECTOR (14)	PINCER
d	REMOVE WIRES OF THE CONTROL GEAR - PSU (8) FROM THE LIGHT SOURCE - HUE CONNECT (5)	FLATHEAD SCREW
е	REMOVE THE CONTROL GEAR - PSU (8) BY UNSCREWING THE SCREWS (9)	CROSS HEA
f	REMOVE FLAT CABLE (11) FROM THE LIGHT SOURCE - HUE CONNECT (5)	-
g	REMOVE LIGHT SOURCE - HUE CONNECT (5) BY UNSCREWING THE SCREW (4)	CROSS HEA
h	REMOVE HEAT SINK (6) FROM THE COVER (3) BY UNSCREWING THE SCREWS (7)	CROSS HEA
i	REMOVE THE LIGHT SOURCE - LED MODULE (12) BY UNSCREWING THE SCREWS (13)	CROSS HEA

		Tools needed			
		-			
10) BY UNSCREWING THE SC	REWS (2)	CROSS HEAD SCR	EW DRIVER		
DR (14)		PINCER			
AR - PSU (8) FROM THE LIGH	T SOURCE - HUE CONNECT (5)	FLATHEAD SCREWDRIVER OF	RWAGO TOOL #2065		
) BY UNSCREWING THE SCR	EWS (9)	CROSS HEAD SCR	EW DRIVER		
IGHT SOURCE - HUE CONNE	CT (5)	-			
CT (5) BY UNSCREWING THE	SCREW (4)	CROSS HEAD SCR	EW DRIVER		
VER (3) BY UNSCREWING TH	E SCREWS (7)	CROSS HEAD SCR	EW DRIVER		
DULE (12) BY UNSCREWING	THE SCREWS (13)	CROSS HEAD SCR	EW DRIVER		
STATUS DESCRIPT	ION		DESIGN ID		
STATUS					
Attrac	lantern Black 1x8W 24V		DOC 12NC		
2021-04-12					
NAME JZ	LOCAL PART ID	SH. 1	SH.		A3-P
CHECKED	DATE		CONFIDENTIAL, PROPE	RTY OF: © 2020 Signify Hold	ling

SKU	Color	Country
915005842401	BLACK	EU