


PHILIPS

Maxos universal


LL515S Blind Unit



IP20










910925869521 LL515Z BC UNIV WH



Compatibility list

SYSTEM	SPRING
Regent	A
Regiolux SDT	
Ridi VLT XX	
Siemens/Siteco 5LS	
Trilux E-Line	B
Siteco Modario	
Zumtobel ZX2	



Install only with power off and removed pre-installed cables from the trunking!






583 - 442710483500

2023-06-09
© Signify Holding
All rights reserved




Installation is prohibited into heavily worn trunking!



1


Spring A
(pre-installed)



2a




Spring B
(install spring B, then remove spring A)



2b





Through wire (with spring A or B, not included in box)






3



910925869522 LL515Z WIRING 5x1.5 UNIV WH
910925869523 LL515Z WIRING 7x1.5 UNIV WH



4



5



2x

DONE!

6


1



Scan me!



2



Register me!

SCAN



To get an overview of all spare parts for a luminaire, please refer to detailed instructions in the service manual available via the Signify Service tag apps (Android and iOS).





© 2023 Signify Holding

All rights reserved. This document contains information relating to the product portfolio of Signify which information may be subject to change. No representation or warranty as to the accuracy or completeness of the information included herein is given and any liability for any action in reliance thereon is disclaimed. The information presented in this document is not intended as any commercial offer and does not form part of any quotation or contract. Philips and the Philips Shield Emblem are registered trademarks of Koninklijke Philips N.V.. All other trademarks are owned by Signify Holding or their respective owners.

Signify Holding
The Netherlands