

INSTALLATION INSTRUCTIONS


SFRP - YOKE MOUNT ON \varnothing 3.00" X 4" TENON

IMPORTANT: READ ALL INSTRUCTIONS BEFORE PERFORMING ANY WORK.
BE SURE ALL POWER IS OFF PRIOR TO INSTALLING LUMINAIRES.

WARNING: FIXTURE MUST BE GROUNDED IN ACCORDANCE WITH APPROPRIATE CODES.
FAILURE TO DO SO MAY RESULT IN SERIOUS INJURY.

1. Pull field wires through the pole top tenon allowing sufficient length of leads above the pole top tenon to make electrical connections.
2. Remove (4) #8-32 top cover retaining screws and remove yoke top cover.
3. Fit yoke assembly onto the pole top tenon. **See page 2 if adapter is required.**
4. Determine desired orientation of luminaire and secure in position with (4) 1/4-20 allen set screws.
5. Splice field wires to luminaire leads (input and grounding) and secure inside pole top tenon with wire tie(s) (by others).
6. Replace yoke top cover on yoke assembly and secure using (4) #8-32 screws.
7. Installing photocontrol (where applicable). Loosen two screws on top of photocontrol receptacle and rotate receptacle until "North" arrow on receptacle points North. Make sure receptacle is centered in its mounting hole tighten screws and install photocontrol.
8. Install bird deterrent if applicable, (See page 3).
9. Energize system.

SFRP - YOKE MOUNT ON \varnothing 3.00" X 4" TENON




INSTALLATION INSTRUCTIONS

SFRP - YOKE MOUNT ON \varnothing 2-3/8" X 4" TENON

IMPORTANT: READ ALL INSTRUCTIONS BEFORE PERFORMING ANY WORK.
BE SURE ALL POWER IS OFF PRIOR TO INSTALLING LUMINAIRES.

WARNING: FIXTURE MUST BE GROUNDED IN ACCORDANCE WITH APPROPRIATE CODES.
FAILURE TO DO SO MAY RESULT IN SERIOUS INJURY.

1. Use adapter if pole top tenon is \varnothing 2-3/8.
2. Fit tenon adapter onto tenon and secure with provided 1/4-20 set screws.
3. Continue step 3 on page 1.



INSTALLATION INSTRUCTIONS

SFRP - YOKE MOUNT WITH BIRD DETERRENT

IMPORTANT: READ ALL INSTRUCTIONS BEFORE PERFORMING ANY WORK.
BE SURE ALL POWER IS OFF PRIOR TO INSTALLING LUMINAIRES.

WARNING: FIXTURE MUST BE GROUNDED IN ACCORDANCE WITH APPROPRIATE CODES.
FAILURE TO DO SO MAY RESULT IN SERIOUS INJURY.

