



# MultiOne


by **signify**

Release notes

MultiOne

Configuration tooling

## MultiOne Engineering v3.25



## Release Notes June 2023

In this release the following items were changed (compared to the previous version)

## CHANGES

- New Virtual Devices
- Renamed the SR PSU feature to DALI Power Supply
- Solved some minor bugs

Device Name	Version	12NC
<b>Xitanium 12W 0.08-0.5A 24V 230V</b>	2,0	929003416106
<b>Xitanium 23W 0.15-0.7A 38V 230V</b>	2,0	929003416206
<b>Xitanium 35W 0.08-0.35A 220V S21 230V</b>	1.0	929002934306
<b>Xitanium 60W 0.08-0.35A 300V S21 230V</b>	1.0	929002934506
<b>Xitanium 60W 0.15-0.5A 220V S21 230V</b>	1.0	929002934406
<b>Xitanium 90W 0.25-0.7A 220V S21 230V</b>	1.0	929002934606
<b>TrustSight DALI 45-300V LFP+</b>	1.0	929003417806
<b>TrustSight DALI 15-55V LFP+</b>	1.0	929003417906
<b>TrustSight DALI 45-300V NiMH+</b>	1.0	929003418706
<b>TrustSight DALI 15-55V NiMH+</b>	1.0	929003418806
<b>Xitanium 36W 0.3-1.0A 54V TD S 230V G2</b>	1.0	929002957606
<b>Xitanium 75W 0.7-2.0A 54V TD S 230V G2</b>	1.0	929002957706
<b>Xi 1100W 1.6-3.8A SR 277-347-400V GV2</b>	1.0	929002956906
<b>Xi 765W 1.6-3.8A SR 277-347-400V GV2</b>	1.0	929002962806
<b>Xi EP LV 250W 4.0-8.3A WL I215</b>	1.0	929003393080
<b>Xi EP LV 250W 4.0-8.3A 1-10V WL I215</b>	1.0	929003393880
<b>Xi EP LV 65W 0.9-2.2A WL I120</b>	1.0	929003392680
<b>Xi EP LV 100W 1.3-3.4A WL I155</b>	0.1	929003392780
<b>Xi EP LV 150W 2.0-5.0A WL I175</b>	0.1	929003392880
<b>Xi EP LV 200W 3.0-6.7A WL I195</b>	0.1	929003392980
<b>Xi EP LV 65W 0.9-2.2A 1-10V WL I120</b>	0.1	929003393480
<b>Xi EP LV 100W 1.3-3.4A 1-10V WL I155</b>	0.1	929003393580
<b>Xi EP LV 150W 2.0-5.0A 1-10V WL I175</b>	0.1	929003393680
<b>Xi EP LV 200W 3.0-6.7A 1-10V WL I195</b>	0.1	929003393780
<b>Xitanium 12W 0.08-0.5A 24V 230V</b>	3.0	929003456706

<b>XI075C200V048BPT1</b>	1.0	929002757313
<b>XI020C056V054VPT1</b>	1.0	929002763613
<b>Xi FP 150W 0.2-0.7A SNLDAE 230V S240 sXt</b>	3.5	929003458206
<b>Xi FP 75W 0.2-0.7A SNLDAE 230V S240 sXt</b>	3.5	929003458306
<b>Xi FP 75W 0.3-1.0A SNLDAE 230V S240 sXt</b>	3.5	929003458406
<b>Xi FP 150W 0.3-1.0A SNLDAE 230V S240 sXt</b>	3.5	929003458506
<b>Xi FP 40W 0.2-0.7A SNLDAE 230V S175 sXt</b>	3.5	929003458606
<b>Xi FP 22W 0.3-1.0A SNLDAE 230V S175 sXt</b>	3.5	929003458706
<b>Xi FP 40W 0.3-1.0A SNLDAE 230V S175 sXt</b>	3.5	929003458806
<b>Xitanium 42W/a 0.3-1.05A 48V TD 3CW</b>	1.0	929003425706
<b>Xitanium 42W/a 0.3-1.05A 48V TD 3CB</b>	1.0	929003425806
<b>Xitanium 42W/a 0.3-1.05A 48V TD 3CG</b>	1.0	929003425906

## IMPORTANT NOTICE

Make sure that also the extra conditions are fulfilled:

- Put the Power mode of your PC settings in best performance.
- The correct Microsoft Windows version,
  - Tested on Windows 10 and Windows 11

The MultiOne software package is released for most virus scanners