



MultiOne


by **signify**

Release notes

MultiOne

Configuration tooling

MultiOne Workflow v3.32



Release Notes March 2025

In this release, the following items were changed (compared to the previous version):

CHANGES

- New Feature Version
 - Luminaire Info (extended with format 4 and 5)
- Solved minor bugs
- New virtual devices

Device Name	Version	12NC
Xi 1160W 1.6-4.0A WDU 277-400V GV2	1.0	929003977106
Xi FP 22W 0.2-0.7A SNLDAE 230V C123 sXt	4.0	929004003806
Xi FP 22W 0.3-1.0A SNLDAE 230V C123 sXt	4.0	929004003906
Xi FP 40W 0.2-0.7A SNLDAE 230V C123 sXt	4.0	929004004006
Xi FP 40W 0.3-1.0A SNLDAE 230V C123 sXt	4.0	929004004106
XI020C070V054BST5	1.0	929002779913
XI030C110V054BST5	1.0	929002780013
Xi 1160W 1.6-4.0A SR 277-400V 4CH C GV2	1.0	929004006606
Xi 1160W 1.6-4.0A WDU 277-400V 2CH GV2	1.0	929003976806
Xi LP 40W 0.3-1.05A S1 WL I125	1.0	929003876580
Xi LP 65W 0.3-1.05A S1 WL I125	1.0	929003876680
Xi LP 65W 0.3-1.05A S1 WL I125 TR	1.0	929003912480
Xi LP 65W 0.3-1.05A S1 WL I125 TR2	1.0	929004829601
STS LP 40W 0.3-1.05A S1 WL I125	1.0	929003935701
STS LP 65W 0.3-1.05A S1 WL I125	1.0	929003935801

Hardware Notification

Please note for device Xi CR 110W 0.2-1.05A SDMP 230V C133 sXt with 12NC:929003975006 you must use v3.32 as there were minor changes done for the feature DTL.

IMPORTANT NOTICE

Make sure that also the extra conditions are fulfilled:

- Put the Power mode of your PC settings in best performance.
- The correct Microsoft Windows version,
 - Tested on Windows 10 and Windows 11

The MultiOne software package is released for most virus scanners