


Release notes

MultiOne

Configuration tooling

# MultiOne Workflow v3.20



Release Note



In this release the following items were changed (compared to the previous version):

## **CHANGES**

#### o Added:

Support for new (versions of) LED devices

name	versio	12nc
	n	
SNH210IA	6.3	929002859806
LDP 150W 0.3-1.05A IP67 WL	3.2	929003403480
LDP 65W 0.3-1.05A IP67 WL	1.0	929003403380
LDP-200M305 0.3-1.05A IP67 WL	3.2	929003403580
LDP-240M368 0.3-1.05A IP67 WL	1.0	929003403680
Xi FP 110W .27A SNLDAE 230 C133 TR sXt	1.0	929002846080
Xi FP 110W .3-1A SNLDAE 230 C133 TR sXt	1.0	929002846180
Xi FP 150W .27A SNLDAE 230 S240 TR sXt	1.0	929002814380
Xi FP 150W .3-1A SNLDAE 230 S240 TR sXt	1.0	929002845980
Xi FP 165W .3-1A SNLDAE 230 C170 TR sXt	1.0	929002846480
Xi FP 165W .3-1A SNLDAE 230 C170 TR sXt	2.0	929002889806
Xi FP 165W 0.2-0.7A SNLDAE 230V C170 sXt	2.0	929002874906
Xi FP 165W 0.3-1.0A SNLDAE 230V C170 sXt	2.0	929002875006
Xi FP 40W .27A SNLDAE 230 C123 TR sXt	1.0	929002846280
Xi FP 40W .27A SNLDAE 230 S175 TR sXt	1.0	929002814180
Xi FP 75W .27A SNLDAE 230 S240 TR sXt	1.0	929002814280
Xi FP 75W .3-1A SNLDAE 230 C133 TR sXt	1.0	929002846380
Xi LP 100W 0.3-1.05A S1 WL I155	3.2	929002878980
Xi LP 100W 0.3-1.05A S1 WL I155 CF	3.2	929003387080
Xi LP 100W 0.5-1.5A S1 WL I155	3.2	929002879280
Xi LP 100W 0.5-1.5A S1 WL I155 CF	3.2	929003387380
Xi LP 150W 0.3-1.05A S1 WL I175	3.2	929002879080
Xi LP 150W 0.3-1.05A S1 WL I175 CF	3.2	929003387180
Xi LP 150W 0.5-1.5A S1 WL 1175	3.2	929002879380
Xi LP 150W 0.5-1.5A S1 WL I175 CF	3.2	929003387480
Xi LP 200W 0.3-1.05A S1 WL I195	3.2	929002879180
Xi LP 200W 0.3-1.05A S1 WL I195 CF	3.2	929003387280
Xi LP 200W 0.5-1.5A S1 WL I195	3.2	929002879480
Xi LP 200W 0.5-1.5A S1 WL I195 CF	3.2	929003387580
Xi LP 250W 0.3-1.05A S1 WL I215	1.0	929003389180
Xi LP 250W 0.3-1.05A S1 WL I215CF	1.0	929003389380
Xi LP 250W 0.5-1.5A S1 WL B215	1.0	929003389580
Xi LP 250W 0.5-1.5A S1 WL I215	1.0	929003389280
Xi LP 250W 0.5-1.5A S1 WL I215CF	1.0	929003389480
Xi LP 320W 0.7-2.1A S1 WL AUX I230	1.0	929002882780
Xi LP 40W 0.3-1.05A S1 WL I122	1.0	929003388680
Xi LP 65W 0.3-1.05A S1 WL I122	1.0	929003388780



Xi LP 65W 0.3-1.05A S1 WL I122CF	1.0	929003388980
Xi LP 65W 0.5-1.5A S1 WL I122	1.0	929003388880
Xi LP 65W 0.5-1.5A S1 WL I122CF	1.0	929003389080
XI020C050V048BPT1	1.0	929002735113
XI030C075V048BPT1	1.0	929002735213
XI040C100V048BPT1	1.0	929002735313
XI050C140V048BPT1	1.0	929002735413
Xitanium 12W 0.08-0.5A 25V SR 230V	1.0	929002880406
Xitanium 20W WH 0.15-0.5A 54V SR Is 230V	1.0	929002861106
Xitanium 23W 0.15-0.7A 41V SR 230V	1.0	929002880506
Xitanium 36W 0.3-1.0A 54V TD 230V G2	1.0	929001696006
Xitanium 36W WH 0.15-1.05A 54V TD/Is	1.0	929002861906
Xitanium 36W WH 0.3-1.05A 54V SR Is 230V	1.0	929002861206
Xitanium 50W WH 0.7-1.5A 54V SR Is 230V	1.0	929002861306
Xitanium 50W WH 0.7-1.5A 54V TD/Is	1.0	929002862006
Xitanium 75W 0.7-2.0A 54V TD 230V G2	1.0	929001696106

## Improved functionality

- o Solved some minor bugs.
- o Added new DTL Lock feature
- Support for new SimpleSet reader LCN9640 (FEIG naming: ID ISC.LR(M)1002 with ID ISC.ANT310/310)

### **IMPORTANT NOTICE**

Make sure that also the extra conditions are fulfilled:

- Put the *Power mode* of your PC settings in *best performance*.
- The correct Microsoft Windows version,
  - No Windows XP support
  - When running the installer on Windows 10, a 'Do not run' button might be shown as the application is not signed. Go to 'more info' to force installation.

The MultiOne software is tested on a wide variety of virus scanners (latest versions), no issues detected.

Document: 02-06-2021 No: RNW8 2021v2 Author: E. Bos

